



## CASE STUDY : PHOSCRETE VO

### Bridge Beam Repair



**Location:** [CA-70 Bridge, Oroville, CA](#)

**Ambient Temperature:** [65°F, Sunny](#)

**Agency:** Sacramento County Department of Transportation

**Contact:** Craig Bollig, Highway Maintenance Supervisor, [Bollig@saccounty.net](mailto:Bollig@saccounty.net)

**Installation Date:** 03 November 2016

[Link to Google Photos Album](#)

**Installation Notes:** Bridge beam was damaged by a vehicle. Site was prepared and cleaned. Phoscrete was installed first with a scrub coat, then in lifts. Using standard tools and water as a bond breaker, the repair was quickly smoothed and finished.