




# CASE STUDY : PHOSCRETE HC

## Bridge Deck Patches



**Location:** [Stockton Channel Bridge, CA](#)

**Ambient Temperature:** [35°F Night](#)

**Agency:** Caltrans District 10

**Contact:** Greg Heath, Bridge Maintenance Supervisor, [greg.heath@dot.ca.gov](mailto:greg.heath@dot.ca.gov)

**Installation Date:** 19 December 2016

[Link to Google Photos Album](#)

**Installation Notes:** Heavy traffic runs on this I-5 bridge across Stockton Channel. Aerial view shows a mess of bubble-gum deck patches in various states of failure. Phoscrete was installed on multiple spalls on a cold Sunday night in 2016. Demolition began at 11PM, Phoscrete was poured at 2AM and all patches were completed by 3AM, The interstate was ready for Monday traffic before 5am.